ACCESSORIES

Motors
XSDC3EZ228B
XSDC3EZ030B

TRASDC3.120 Switching power supply 2 Amps

Motors

XSDC3EZ128 XSDC3EZ228



TRAS.120 Switching power supply 2,5 Amps



FLAX14W007.L1 (6.102 in) FLAX14W007.L2 (4.803 in) FLAX14W007.L3 (9.606 in)

Power cord extension with plugs (for DC battery motors)



► FLAX13W070

Plug-in power cable for XS50 motor without dry contacts



► FLAX13W065

